

BELZONA PROTECTS RUBBER PIPES AT WWTP FROM UV ATTACK

ID: 681

Industry: Water / Wastewater

Customer Location: Wastewater Treatment Plant, BC,
Canada

Application: VPF-Valves, Pipes and Fittings

Application Date: August 2004

Substrate: Rubber pipe with stainless steel flanges

Products: * Belzona® 3211 (Lagseal) ,
* Belzona® 3921 (GSC Conditioner) ,

Problem

UV attacks the rubber over a period of time causing it to degrade and eventually become brittle.



Photograph Descriptions

- * Preparation of flexible hoses in progress. All pipes are tightly wrapped with a polythene film to prevent bleed through of the pitch from the rubber component. ,
- * The flanges are ground and coated with Belzona® 3921 GSC Conditioner. ,
- * Application of Belzona® 3211 in progress. Belzona® 9311 Reinforcement cloth is incorporated into the 1st coat. ,
- * Completed application. ,

Application Situation

Flexible rubber transfer pipes on digester

Application Method

Application carried out in accordance with a modified version of Belzona System Leaflet VPF-12.

Belzona Facts

This application has provided protection on similar pipes for more than 10 years. The life of unprotected pipes was 3-5 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve